


DOCKET NO.: 8006-1009
APPLN NO.: 09/972,951
REPLY TO NOTICE OF ALLOWABILITY OF: FEBRUARY 9, 2005
REPLACEMENT SHEET 1 of 8

## FIG. 1



DOCKET NO.: 8006-1009 APPLN NO.: 09/972,951 REPLY TO NOTICE OF ALLOWABILITY OF: FEBRUARY 9, 2005 REPLACEMENT SHEET 2 of 8

FIG. 2






FIG. 3




DOCKET NO.: 8006-1009 APPLN NO.: 09/972,951 REPLY TO NOTICE OF ALLOWABILITY OF: FEBRUARY 9, 2005 REPLACEMENT SHEET 3 of 8

FIG. 4



SCRATCH PREVENTION PANEL STRUCTURE

FIG. 5 (PRIOR ART)



CONVENTIONAL PANEL STRUCTURE

FIG. 6





FIG. 7



DOCKET NO.: 8006-1009 APPLN NO.: 09/972,951 REPLY TO NOTICE OF ALLOWABILITY OF: FEBRUARY 9, 2005 REPLACEMENT SHEET 5 of 8

FIG. 8 (PRIOR ART)





FIG. 9








FIG. 11



**FIG. 12** 



**FIG.13** 

